

LP USARC
12 Jan 94

Appendix E
Spill Report

63RD US ARCOM SPILL REPORT

Instructions:

Fill out this report for any spill of more than one gallon or less than one gallon if it enters a water way, storm drain, sewer, pond or other body of water. A copy of this report will be forwarded to the 63rd ARCOM Engineer no later than 24 hours from the discovery of the spill. In addition, contact the 63rd ARCOM Engineer no later than the 1st working day after the spill.

Fill out the following information:

Unit 663 RD ENG. CO.

Date OCT. 22, 1993

Submitted by: CW2 MATTINGLY Duty Section: TOPO

Location of Spill UNDERCARRIAGE OF
CAMERA VAN

Description of Spill PHOTOGRAPHIC WASTE
LEAKING FROM SINK INSIDE
OF THE VAN. FLOORBOARDS ARE
ROTTEN THRU SO SPILLS INSIDE
OF VAN LEAK TO THE
OUTSIDE

Hazardous Material/Waste Involved 2 GALLONS OF
LIQUID WASTE
95% WATER
5% PHOTOGRAPHIC WASTE
CONTAINING SILVER
NITRATE

Appendix E
Spill Report

Spill Containment Measures Taken AS SOON AS LEAK
STARTED A KITTY LITTER
COMPOUND WAS SPREAD
OVER THE GROUND AND
SWEEPED UP WHEN LEAK
STOPPED. LITTER PUT IN
WASTE CONTAINMENT AREA
FOR PICK-UP

Was outside assistance required YES ___ NO X

If yes, who:

Name

Organization

Phone Number

Further Comments VAN IS SCHEDULED TO BE
REPAIRED AS SOON AS POSSIBLE

Measures Taken to Prevent Recurrence VAN IS TO BE REPAIRED
& CHASS GIVEN ON
SPILL CLEAN-UP

LB USARC
12 Jan 94

Appendix E
Spill Report

63RD US ARCOM SPILL REPORT

Instructions:

Fill out this report for any spill of more than one gallon or less than one gallon if it enters a water way, storm drain, sewer, pond or other body of water. A copy of this report will be forwarded to the 63rd ARCOM Engineer no later than 24 hours from the discovery of the spill. In addition, contact the 63rd ARCOM Engineer no later than the 1st working day after the spill.

Fill out the following information:

Unit 663RD ENG. CO.

Date NOV. 14, 1993

Submitted by: CW2 MATTINGLY Duty Section: TOPD TECH.

Location of Spill OUTSIDE OF PLD ROOM

Description of Spill 1 PT. OF LUBRICATING OIL

Hazardous Material/Waste Involved NONE

Appendix E
Spill Report

Spill Containment Measures Taken AS SOON AS SPILL
ACCURED AN ABSORBENT
MATERIAL WAS SPREAD
OUT FOR SOAKAGE

Was outside assistance required YES____ NO X

If yes, who:

Name	Organization	Phone Number
-----	-----	-----
-----	-----	-----
-----	-----	-----

Further Comments _____

Measures Taken to Prevent Recurrence SPILL TRAYS NOW
BEING USED WHEN
FILLING OIL CANS